

SCREENING SITE INSPECTION WORK PLAN  
FOR

ESSEX GROUP  
TOPEKA, INDIANA  
U.S. EPA ID: IND040284887  
SS ID: NONE  
TDD: F05-8705-023  
PAN: FIN0607GA

US EPA RECORDS CENTER REGION 5



546618

937732

JANUARY 23, 1989

Elements of this Screening Site Inspection Work Plan are considered confidential and pre-decisional in nature. Material and information contained within this report may not be released without the approval of the United States Environmental Protection Agency Region V Pre-Remedial Unit.



**ecology and environment, inc.**

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-663-9415

International Specialists in the Environment

recycled paper

WORK PLAN **1**

---

SITE MAPS **2**

---

HRS WORKSHEETS **3**

---

APPENDIX **4**

---

REFERENCES **5**

---

## INSPECTION WORK PLAN

THIS DOCUMENT IS CONFIDENTIAL. Due to the predecisional nature of this document, this document and its attachments are not to be released without prior approval of the United States Environmental Protection Agency (U.S. EPA).

This site inspection work plan (WP) has been prepared by Ecology and Environment, Inc., or its subcontractor, C. C. Johnson and Malhotra, P.C., under the field investigation team (FIT) contract with U.S. EPA (No. 68-01-7347).

The objectives of this WP are to:

- o Prepare a preliminary Hazard Ranking System (HRS) score using HRS 1 (40 CFR 300, July 16, 1982) criteria based on existing file information (Part C of WP);
- o Prepare projected HRS 1 scores based on experience and professional judgment (Part C of WP);
- o Identify HRS 1 score data gaps (Part E of WP); and
- o Propose site inspection activities to satisfy the HRS 1 score data gaps; technical approach and estimated LOE are provided (Parts E and I, respectively).

Unless otherwise stated, QA/QC protocol for site inspection activities is documented in the Quality Assurance Project Plan Region V FIT Conducted Site Inspections - May 1, 1987.





INDIANA DEPARTMENT OF ENVIRONMENTAL MANAGEMENT

RECEIVED  
FEB 22 1990

TECHNICAL SUPPORT  
SECTION

RECEIVED

FEB 23 1990

Pre-Remedial  
Unit

105 South Meridian Street  
P.O. Box 6015  
Indianapolis 46206-6015  
Telephone 317/232-8603

February 19, 1990

Dr. Don Josif, 5-HSM-12  
Pre-Remedial Unit  
U.S. Environmental Protection Agency  
Region V  
230 South Dearborn Street  
Chicago, IL 60604

Re: Essex Group, Inc.  
SSI Workplan  
IND040284887  
Lagrange County

Dear Dr. Josif:

The screening site inspection for the aforementioned site was reviewed by staff. It is staff's opinion that a screening site inspection is not needed for this site.


The preliminary assessment was completed February 26, 1986. The preparer stated that a site inspection should not occur until RCRA action was completed. A review of the State files revealed Essex Group, Inc. (formerly United Technologies Automotive) hired an environmental consultant to perform soil excavation and sampling at the site. Samples were analyzed for EPA priority pollutants, base/neutral organics, acid extractable organics and eight total metals for the EP-toxicity test. Sampling and soil excavations occurred November 25, 1986 and December 22, 1986. Nishikawa Standard Co., the current owner and operator of the facility, obtained a separate environmental consultant to collect samples during the same times as the Essex Group consultant. Nishikawa also instructed their consultant to install four (4) monitoring wells. All sampling results were comparable, with negligible concentrations of toluene, tetrachloroethylene and 1,1,1-trichloroethane. The groundwater was contaminated with low levels of 1,1,1-TCA and dichloroethane. Soil disposal was made off-site at Chemical Waste Disposal in Fort Wayne, Indiana.

Dr. Josif  
Page 2  
February 19, 1990

Staff from IDEM Chemical Evaluation Section reviewed the report and sampling results submitted by the environmental consultants. Staff stated that because the levels of contamination were well below the regulatory limits, the site did not pose a threat to the environment. The clean-up was deemed adequate. However, the Geology Section of IDEM is requesting continued groundwater monitoring because of the presence of 1,1,1-TCA and dichloroethane. Concern was also expressed over the placement of the monitoring wells. Thus, the RCRA investigation is continuing.

For these reasons, the State does not recommend pursuing a screening site inspection for this facility. If there are any questions, please contact myself or Ms. Dana Reed Wise at AC 317/232-8930.

Very truly yours,

A handwritten signature in black ink, appearing to read "Harry E. Atkinson". The signature is fluid and cursive, with a large initial "H" and "A".

Harry E. Atkinson, Chief  
Site Investigation Section  
Policy and Planning Branch  
Solid and Hazardous Waste Management

DRW/drw

## WORK PLAN



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5

230 SOUTH DEARBORN ST.

CHICAGO, ILLINOIS 60604

REPLY TO THE ATTENTION OF

5HR-11

Harry Atkinson, Chief  
Site Investigation Section  
Office of Solid and Hazardous Waste  
Indiana Department of Environmental  
Management  
105 South Meridian Street  
Indianapolis, Indiana 46306-6015

Site Name Essex Group

Location: Topshel, IN

Identification No. IND 010284887

Date: JAN 29, 1990

Dear Mr. Atkinson:

Attached is a copy of the site inspection work plan which has been prepared for the site listed above. This document is considered to be draft and subject to changes and modifications based on actual conditions which may be encountered at the site.

Because this is considered to be a draft document, it should be for official use only and should not be distributed outside of your agency without prior notification and approval of the U.S. Environmental Protection Agency.

The document also contains a preliminary estimate of the Hazard Ranking System (HRS) score for the site and a project score based on specific assumptions as addressed in the work plan. This information is considered predecisional. Therefore, it should not be released. Your field and district staff especially should be made aware of the predecisional nature of this score, the legal implications of releasing it relative to the National Priorities List (NPL) candidacy process, and therefore the need not to release any score. If you have any questions concerning release of this information, please contact Ms. Jeanne Griffin, of my staff, at (312) 886-3007.

If you have any comments on the work plan itself, please contact the appropriate FIT State Coordinator at (312) 633-9415 and Mr. Charles Castle, of my staff, at (312) 886-5892, within ten working days. If we do not receive any comments written or verbal from you, then you will be contacted at the end of the ten day comment period.



A. GENERAL INFORMATION

CERCLIS SITE NAME: ESSEX GROUP  
ALSO KNOWN AS: UNITED TECHNOLOGIES  
FORMERLY KNOWN AS: LAND LIBERTY HOMES  
ADDRESS: MORROW AVE. AND INDIANA ST. (P.O. Box 248)  
CITY: TOPEKA  
STATE: IN  
COUNTY: LAGRANGE  
ZIP CODE: 46571  
U.S. EPA ID: IND 040284887  
SS ID: NONE  
TDD: F05 8705 023  
PAN: FIN0607 GA

FIT USE ONLY

WORK PLAN TYPE: ☒ SCREENING SITE INSPECTION (SSI) WORK PLAN

OTHER: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

PREPARED BY: ED KARECKI (FIT)

DATE: 12/17/89

REVIEWED BY: [Signature] (FIT)

DATE: 12/29/89

APPROVED BY: [Signature] (FIT)

DATE: 1/8/90

U.S. EPA USE ONLY

REVIEWED BY: [Signature]

(U.S. EPA)

DATE: 2-17-90

☐ WORK PLAN APPROVED. Recommend issuance of TDD to implement the Work Plan.

☒ WORK PLAN APPROVED. No Further Remedial Action Planned (NFRAP).

☐ WORK PLAN REJECTED.

COMMENTS: See also ITEM 2-19-90 letter  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

## B. SITE INFORMATION

This section of the WP presents current and historical information pertaining to the site, including: site operations, storage/disposal methods, site property area, site status, owners and operators, permit information, and response/enforcement activities. A site location map is shown on Figure 1, located in Section 2.

### 1. Site Operations (past and present; check all that apply):

<input checked="" type="checkbox"/> Aboveground storage	<input type="checkbox"/> Mining site
<input type="checkbox"/> Belowground storage	<input type="checkbox"/> Open dump
<input type="checkbox"/> Chemical manufacturer	<input type="checkbox"/> Ore processor
<input type="checkbox"/> Drum recycler	<input type="checkbox"/> Physical/chemical treatment
<input type="checkbox"/> Electroplater	<input type="checkbox"/> Recycler/reclaimer
<input type="checkbox"/> Foundry	<input type="checkbox"/> Surface impoundment
<input type="checkbox"/> Incinerator	<input type="checkbox"/> Underground injection
<input type="checkbox"/> Landfarm	<input type="checkbox"/> Well field
<input type="checkbox"/> Landfill	<input type="checkbox"/> Wood preserver
<input type="checkbox"/> Midnight dump	<input type="checkbox"/> Other: _____
	_____
	_____

References: 2 , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_

### 2. Storage/Disposal Methods (past and present; check all that apply):

	Waste Quantity (amount/units of measure)
<input checked="" type="checkbox"/> Drums, aboveground	<u>~22 DRUMS</u>
<input type="checkbox"/> Landfarm	_____
<input type="checkbox"/> Landfill	_____
<input type="checkbox"/> Open dump	_____
<input type="checkbox"/> Piles	_____
<input type="checkbox"/> Surface impoundment	_____
<input type="checkbox"/> Tank, aboveground	_____
<input type="checkbox"/> Tank, belowground	_____
<input type="checkbox"/> Other: _____	_____
	_____

References: 2 , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_

### 3. Site Property Area: 18.4 (acres)

References: 10 , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_

### 4. Site History/Description and Unusual Features: (see following page.)

References: 2 , 10 , 13 , \_\_\_\_\_ , \_\_\_\_\_

## SITE HISTORY (Continued)

ESSEX GROUP INC. OWNS UNITED TECHNOLOGIES, WHICH IS AN AUTOMOTIVE ASSEMBLY PLANT. THE PLANT HAS BEEN CLOSED SINCE 1985. THE PLANT WAS IN PRODUCTION FOR ABOUT TEN YEARS. THIS PLANT GENERATED HAZARDOUS WASTES DURING DEGREASING AND CLEANING OF THEIR AUTOMOTIVE WIRE ASSEMBLIES. DURING STATE INSPECTIONS A TOTAL OF 22 DRUMS WERE FOUND ON SITE. NOT ALL DRUMS WERE MARKED AND SOME WERE LEAKING. SPILLED MATERIAL WAS VISIBLE ON THE GROUND. THE WASTES PRODUCED ON SITE WERE PRIMARILY SOLVENTS AND LUBE OILS. IT IS REPORTED THAT UPON CLOSURE OF THE PLANT THE DRUMS WERE REMOVED AND DISPOSED OF BY CHEMICAL WASTE MANAGEMENT. IT IS REPORTED THAT VIOLATIONS WERE ISSUED BY RCRA.

THE SITE IS ADJACENT TO A WETLAND. THE CITY OF TOPEKA HAS MUNICIPAL WELLS LESS THAN ONE MILE FROM THE SITE.

THE SITE IS CURRENTLY OWNED BY NISHAKAWA STANDARD INC. WHICH MANUFACTURES RUBBER WEATHERSTRIPPING.

5. Site Status: ☒ Active ☐ Inactive

References: 13 , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_

6. Owner/Operator History

Current Owner

Name: SAFELY AS OPERATOR  
Address: \_\_\_\_\_

City, State, Zip Code: \_\_\_\_\_

Years of Ownership: 2

Current Operator

Name: MISHAKAWA STANDARD CO.  
Address: MORROW AVE + INDIANA ST.

City, State, Zip Code: \_\_\_\_\_

TOPEKA, IN 46571

Type of Operation: UNKNOWN

Years of Operation: 2

Previous owners  
(list most recent first)

Name: ESSEX GROUP, INC.  
Address: 5200 AUTO CLUB DRIVE

City, State, Zip Code: DEARBORN,

MI 46571

Years of Ownership: 12

Previous operators  
(list most recent first)

Name: SAFELY  
Address: \_\_\_\_\_

City, State, Zip Code: \_\_\_\_\_

Type of Operation: \_\_\_\_\_

Years of Operation: 10

Name: LAND LIBERTY HOMES  
Address: UNKNOWN

City, State, Zip Code: \_\_\_\_\_

Years of Ownership: UNKNOWN

Name: SAFELY  
Address: \_\_\_\_\_

City, State, Zip Code: \_\_\_\_\_

Type of Operation: TRAILER CO.

Years of Operation: UNKNOWN

References: 10 , 2 , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_

7. Permit Information

Effective Date

Expiration Date

☐ NPDES

☐ UIC

☐ AIR

☒ RCRA, ☐ PART A ☐ PART B

☐ SPCC PLAN

☐ STATE (specify): \_\_\_\_\_

☐ LOCAL (specify): \_\_\_\_\_

☐ OTHER (specify): \_\_\_\_\_

☐ NONE

N/A

N/A

References: 2 , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_

8. Response Activities (previous and current site remediation; check all that apply):

<input type="checkbox"/> Water supply closed	<input type="checkbox"/> Cutoff trenches/sump
<input type="checkbox"/> Temporary water supply provided	<input type="checkbox"/> Subsurface cutoff wall
<input type="checkbox"/> Permanent water supply provided	<input type="checkbox"/> Barrier wall constructed
<input type="checkbox"/> Spilled material removed	<input type="checkbox"/> Capping/covering
<input type="checkbox"/> Contaminated soil removed	<input type="checkbox"/> Bulk tankage repaired
<input type="checkbox"/> Waste repackaged	<input type="checkbox"/> Grout curtain constructed
<input checked="" type="checkbox"/> Waste disposed elsewhere	<input type="checkbox"/> Bottom sealed
<input type="checkbox"/> On-site burial	<input type="checkbox"/> Gas control
<input type="checkbox"/> In situ treatment	<input type="checkbox"/> Fire control
<input type="checkbox"/> Encapsulation	<input type="checkbox"/> Leachate treatment
<input type="checkbox"/> Emergency waste treatment	<input type="checkbox"/> Area evacuated
<input type="checkbox"/> Cutoff walls	<input type="checkbox"/> Access to site restricted
<input type="checkbox"/> Emergency diking/surface water diversion	<input type="checkbox"/> Population relocated

Other remedial and enforcement activities: NONE

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

References: 2 , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_ , \_\_\_\_\_

9. Documented and Alleged Target Compounds

Documented and alleged target compounds are compiled in Table 1. The documented target compounds are supported by analytical data from previous sampling projects. The alleged target compounds are based on the history of site operations and professional judgment. Documented and alleged target compound locations are shown on Figure 2, located in Section 2.



1 Page Removed  
Non-Responsive

#### D. WORK SUMMARY

Based on the preliminary and projected HRS scores, a site inspection will be performed.

The objectives of the site inspection are to:

- o Provide information to satisfy HRS data gaps;
- o Develop the information base needed to permit U.S. EPA to evaluate the need for future site activities; including: immediate removal measures, additional investigation, or no further action; and
- o Characterize hazardous substances, pollutant dispersal pathways, types of receptors, facility management practices, and potentially responsible parties.

Specific tasks to be conducted during the site inspection are (check all that apply):

- ☒ Interview site owner(s)/representative(s)
- ☒ Take photographs of site and surrounding areas
- ☒ Screen site with safety instrumentation (i.e., HNU, OVA, O<sub>2</sub> meter, explosimeter, radiation detector, cyanide detector)
- ☒ Collect environmental samples
- ☒ Assess the need for Immediate Removal Actions
- ☐ FASP\*
- ☐ Soil gas monitoring\*
- ☐ Well point installations\*
- ☐ Geophysics\*: \_\_\_\_\_ (Specify)
- ☐ OTHER\*: \_\_\_\_\_

\* Rationale for these activities and their impact on HRS data gaps:

---

---

---

---

---

---



## E. PROPOSED SAMPLE PLAN

The HRS data gaps are identified in this section, and a proposed sample plan is developed based on the type of information required.

1. A) HRS data gap(s): No file information is available that would determine if an observed release of TCL compounds or TAL analytes has occurred.

B) Sampling proposed to satisfy HRS data gap(s):

X Soil X Sediment      GW      SW      Air      Waste

C) Sampling procedures (number and types of samples; equipment; methodology): 4 soil, 1 sediment, and 1 potential background sample will be collected. All equipment will be decontaminated between each sampling.

A table of proposed sample descriptions is presented in Table 2, Section 1. A proposed sample location map is presented on Figure 3 in Section 2.

2. A) HRS data gap(s): No file information is available that would determine if an observed release of contaminants to groundwater has occurred

B) Sampling proposed to satisfy HRS data gap(s):

     Soil      Sediment X GW      SW      Air      Waste

C) Sampling procedures (number and types of samples; equipment; methodology): NO residential well samples will be collected, due to the distance of residences from the site. Any potential groundwater threat will be addressed at the LSE stage.

A table of proposed sample descriptions is presented in Table 2, Section 1. A proposed sample location map is presented in Figure 3, in Section 2.

Note: Sample locations and/or the number of samples may be changed or eliminated at the discretion of the site team leader in response to actual site conditions during the course of the inspection.

## E. PROPOSED SAMPLE PLAN

The HRS data gaps are identified in this section, and a proposed sample plan is developed based on the type of information required.

1. A) HRS data gap(s): FI has little information concerning potential air emission sources.
- B) Sampling proposed to satisfy HRS data gap(s):  
       Soil        Sediment        GW        SW        Air        Waste
- C) Sampling procedures (number and types of samples; equipment; methodology): No quantitative air monitoring will be conducted during the SSE. Any potential air emission sources identified during the SSE will be addressed at the LSI stage.

A table of proposed sample descriptions is presented in Table 2, Section 1. A proposed sample location map is presented on Figure 3 in Section 2.

2. A) HRS data gap(s): FI has little information concerning potential surface water contamination.
- B) Sampling proposed to satisfy HRS data gap(s):  
       Soil        Sediment        GW   X   SW        Air        Waste
- C) Sampling procedures (number and types of samples; equipment; methodology): No surface water sampling will be conducted during the SSE. If on site soil/sediment samples indicate possible surface water contamination then surface water samples will be collected at the LSI stage.

A table of proposed sample descriptions is presented in Table 2, Section 1. A proposed sample location map is presented in Figure 3, in Section 2.

Note: Sample locations and/or the number of samples may be changed or eliminated at the discretion of the site team leader in response to actual site conditions during the course of the inspection.

MATRIX (✓)								RATIONALE FOR DETERMINING SAMPLE LOCATION	PARAMETERS <sup>1</sup>					
LOCATION	SOIL	SED	GW	SW	AIR	WSTE	OTHR		A/B/H	Pest/ PCB	VOA	METAL	CN <sup>-</sup>	OTHER
S <sub>1</sub>	X							SOIL CONTAMINATION AT DRUM STORAGE AREA	X	X	X	X	X	
S <sub>2</sub>	X							"	↓	↓	↓	↓	↓	
S <sub>3</sub>	X							SOIL CONTAMINATION ON SITE	↓	↓	↓	↓	↓	
S <sub>4</sub>	X							"	↓	↓	↓	↓	↓	
S <sub>5</sub>	X							"	X	X	X	X	X	
S <sub>6</sub>	X							POTENTIAL BACKGROUND SAMPLE	X	X	X	X	X	
											</			

<sup>1</sup>Target Compound List Attached

**Table 2**  
**PROPOSED SAMPLE DESCRIPTIONS**  
(INCLUDING ALL LABORATORY BLANKS AND DUPLICATES)

#### F. COMMENTS

An SSI will be conducted to determine if TCL compounds or TAL analytes exist in on site soils, sediments, or area groundwaters.

#### G. HEALTH AND SAFETY

Proposed E & E Health and Safety protocol to be followed during site inspection.

1. Anticipated level of protection:      A      B      C X D
2. Level of protection modifications: Site will be entered in level D with an upgrade to level C if monitoring equipment detects an increased hazard.
3. Work limitations (time of day, etc.): Work daylight hours only (12 max); monitor for heat/cold stress, observe the buddy system at all times.

#### H. TYPE OF DELIVERABLE


Proposed report format to be submitted to U.S. EPA.


1. X SSI Report including U.S. EPA 2070-13 Form ..
2.      Letter Report
3.      Other

SUBTASK CODE	SUBTASK																					
	General Non-Specific	File Search/Review	Work Plan	Safety Plan	QAPP	Mobilization/Demobilization	Travel	Non-Sampling Field Work	Sample Management	Field Sampling	Screening/Analytical	Subcontract	Meteorologic/Air Sampling Studies	Geophysical Work	Hydrogeological Work	Data Processing/Modelling	Data Validation	Draft Final Deliverable	Internal QA Review	Final Deliverable	Respond To Comments	
	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	TOTAL
TEAM LEADER	24	22				4	11	4		4								60		24		153
SAFETY OFFICER				16		4	11	4		4												39
SAMPLER						4	11		60													75
TEAM MEMBER						4	11	4		4												23
TEAM MEMBER						4	11	4		4												23
ADMINISTRATION	2					2			4													8
EDIT/PUBLISH																		30		10		40
QA				8													6		25			39
TOTALS FOR PROJECT	26	22		24		22	55	16	64	16							6	90	25	34		400

**I. ESTIMATED LOE HOURS**  
 SUMMARY OF PROJECTED HOURS NEEDED TO IMPLEMENT  
 SITE INSPECTION AND COMPLETE SITE INSPECTION REPORT.







**ecology and environment, inc.**


111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-653-0415

<b>TITLE</b> DOCUMENTED/ALLEGED TARGET COMPOUND MAP		<b>FIGURE #</b> 2
<b>SITE</b> ESSEX GROUP		<b>SCALE</b> 1:24000
<b>CITY</b> TOPEKA	<b>STATE</b> IN	<b>P.A.N.</b> FIN0607GA
<b>SOURCE</b> ECOLOGY AND ENVIRONMENT INC.		<b>DATE</b> 1959 <b>REVISED</b> 1981



NORFOLK AND WESTERN R.R.

S2 ▲  
DRUM STORAGE AREA




S1 ▲

S5 ▼


BUILDING

S3



BUILDING

S4 ▲




0 200'



**ecology and environment, inc.**

111 WEST JACKSON BLVD., CHICAGO, ILLINOIS 60604, TEL. 312-653-8416

TITLE SAMPLE LOATION MAP (ON-SITE)		FIGURE # 3
SITE ESSEX GROUP		SCALE 1:24000
CITY TOPEKA	STATE IN	P.A.N. FIN0607GA
SOURCE ECOLOGY AND ENVIRONMENT INC.		DATE 1959
		REVISED 1981





## HRS WORKSHEETS

Hazard Ranking System 1  
Score Worksheets

17 pages removed  
non-responsive



Copies of the following addenda have been supplied to the U.S. Environmental Protection Agency and the appropriate state agencies. Refer to these addenda when reviewing this work plan.

Addendum

Title

A

Routine Analytical Services  
Contract Required Detection and  
Quantitation Limits

B

Central Regional Laboratory  
Detection Limits

C

Special Analytical Services Detection Limits  
Drinking Water Samples

D

Special Analytical Services Detection Limits  
High Concentration Samples





## REFERENCE DOCUMENTATION SHEET

Ref. #	DESCRIPTION OF REFERENCE
1	CLIMATIC ATLAS OF U.S., U.S. DEPT. OF COMMERCE, FIGURE 5a and FIGURE 4a, 1979.
2	U.S. EPA, PRELIMINARY ASSESSMENT FOR ESSEX GROUP, COMPLETED BY JULIE HAXTON OF INDIANA STATE BOARD OF HEALTH, 2/26/86
3	U.S. GEOLOGICAL SURVEY, TOPO. MAPS, OLIVERL., TOPEKA, LIGONIER, ALBION QUADS 1:24,000 SCALE, 1959. PHOTOREVISED 1981
4	RAINFALL FREQUENCY ATLAS OF U.S., U.S. DEPT. OF COMMERCE, TECHNICAL PAPER No. 40, FIGURE 8a, 1963

# REFERENCE DOCUMENTATION SHEET

Ref. #	DESCRIPTION OF REFERENCE
5.	Non-Responsive
6.	LAMBRIGHT, FLOYD, OF TOPEKA WATER DEPT. PHONE CONVERSATION WITH ED KARECKI OF E+E, 12/7/89, (219) 593-2300
7	U.S. DEPT. OF COMMERCE, BUREAU OF THE CENSUS, GENERAL POPULATION CHARACTERISTICS OF INDIANA, 1980
8.	U.S. FISH & WILDLIFE SERVICE, LISTING OF ENDANGERED SPECIES, UPDATED 3/30/89

## REFERENCE DOCUMENTATION SHEET

Ref.#	DESCRIPTION OF REFERENCE
9	IN. STATE BOARD OF HEALTH, OFFICE MEMORANDUM FROM HARBERT, ROY, TO RCRA FILE REGARDING UNITED TECHNOLOGIES 11/20/85
10	WIARD, BILLY OF LAGRANGE CO. AUDITOR'S OFFICE, PHONE CONVERSATION WITH ED KARECKI OF E+E 12/8/89 219-463-7816
11	HAGGARD, DORRIS, OF TOPEKA POLICE DEPT. PHONE CONVERSATION WITH ED KARECKI OF E+E, 12/18/89 219-593-2822
12	MILLER, DAN, OF TOPEKA FIRE DEPT., PHONE CONVERSATION WITH ED KARECKI OF E+E, 12/6/89, 219-593-2323

# REFERENCE DOCUMENTATION SHEET

[illegible]

SOURCES AND DATES OF INFORMATION COLLECTION

<u>SOURCE</u>	<u>DATE</u>
1) State Hazardous/Solid Waste Files	<u>1/5/87</u>
2) State Water Files	<u>1-5-87</u>
3) State Air Files	<u>1-5-87</u>
4) State Department of Health	
5) State Geological Survey	
6) State Department of Natural Resources	<u>1-5-87</u>
7) State Fire Marshall	
8) County Department of Health	
9) County Engineer	
10) County Clerk/Recorder of Deeds	
11) City Department of Health	
12) City Engineer	
13) City Fire Department/Fire Marshall	
14) City Water/Sever Department	<u>12-7-89</u>
15) U.S. Soil Conservation Service	
16) Others	
<u>COUNTY AUDITOR</u>	<u>12-8-89</u>
<u>CITY POLICE DEPT.</u>	<u>12-18-89</u>
_____	_____
_____	_____
STATE CONTACT(S): <u>HARRY ATKINSON</u>	<u>317-232-8927</u>
(name)	(phone number)
_____	_____
(name)	(phone number)